

UNITED STATES COAST GUARD

REPORT OF INVESTIGATION INTO THE CIRCUMSTANCES SURROUNDING THE INCIDENT INVOLVING MORNING STAR CRUISES-SEA TREK DIVE DEATH

ON 08/14/2002



MISLE ACTIVITY NUMBER: 1665190 **ORIGINATING UNIT: MSO HONOLULU** MISLE ACTIVITY OWNER: COMMANDANT (G-MRI) MISLE ACTIVITY CONTROLLER: COMMANDANT (G-MRI) MISLE CASE NUMBER: 0



I. INCIDENT BRIEF

Activity 1665190, investigation into SEATREK Diving accident with KBOS/Morning Star Cruises Barge-HA1367, on August 14, 2002 in Kaneohe Bay, Oahu. Female passenger death. No crew or other passengers injured.

SUMMARY-- On August 14, 2002, while diving with the SEATREK system in Kaneohe Bay in 12 feet of water, Mrs. Mitsuko Fukuoka suddenly became "panicky" (exhibit-8 page 3, CG2692) and was assisted to the surface. She was transported to Castle Memorial Hospital. She died two days later (Exhibit-5 page 8).

FINDINGS—Vessel Data:

Name: HA1367CP

Flag: U.S.

Vessel Type: 24FT Barge

Operating Company: Morning Star Cruises, Inc.

49-132 Kamehameha Hwy

Kaneohe, HI 96744 Ph:(808) 239-8886

State of Hawaii: Kaneohe Bay Ocean Recreation Management Area (ORMA) Use Permit-

No. O-KB-12e; Permit valid from June 28, 2002 to June 27, 2003.

Weather:

Air Temp: 75 degrees

Wind: NE Tradewinds at 0-6 mph

Visibility: Good

Involved party information:

- a. Leading, vessel (barge) master, CG license No. Leading, issued December 1998. 9 years experienced master.
- b. dive leader, Safety First CPR/First Aid. Kaneohe, HI.
- c. safety diver, PADI Dive Master. Honolulu, HI.
- d. , barge crew, PADI Dive Master. Mililani, HI.
- e. , barge crew, Honolulu, HI.
- f. ferry boat captain, CG license No. CPR A.E.D. Hauula, HI.
- g. Mitsuko Fukuoka, deceased passenger, Hamakita-Shi, Japan. Age: 43, Height: 5'2", Weight: 130 lbs.
- h. husband of victim. Hamakita-Shi, Japan.
- 1. On August 14, 2002, Mrs. Mitsuko Fukuoka, a 43 year old female passenger on the Morning Star Cruises barge (HA1367) became distressed while diving with the surface supplied air 'SEATREK' helmet in Kaneohe Bay, HI. She was in approximately 12 feet of water and had been diving for about 5 minutes, when according to the dive guide, Mr. she started giving him hand signals indicating "trouble" (Exhibit-8 CG-2692 Report of Accident, Injury or Death).
- 2. The operator, Kaneohe Bay Ocean Sports (KBOS) a division of Morning Star Cruises, had a valid state use permit in-effect on the date of the incident.

- 3. The SEATREK helmet is used for underwater walking and provides positive pressure supply of air from a compressor located on the barge via a 75ft tether. The helmet is 80 lbs, white and is made of ceramic; there are no engravings or serial number on it (Exhibit-9 DOCARE Property Report).
- 4. Safety diver, Mr. escorted Mrs. Fukuoka to the vessel's ladder about 20 yards away to bring her to the surface. At the ladder she went "limp" and had to be carried to the surface by Mr. (Exhibit-2 statement).
- 5. When the helmet was removed, blood and water started coming out of Mrs. Fukuoka's nose. There was no water in the helmet. While being transported to shore via small boat, she stopped breathing and CPR was conducted by employees, Mr. and Mr. (Exhibits 3 and 4, statements of and and Mr.)
- 6. Mrs. Fukuoka was transported to Castle Memorial Hospital, and later that evening, to the Kuakini Decompression Chamber for sickness treatment which had no effect (Exhibit-5 DOCARE Case Report pages 7 & 8). Subsequently, she died two days after the incident. The autopsy revealed that the manner of death was accidental, and listed Asphyxia by drowning as the immediate cause of death. Contributing causes of death were Ischemic heart disease and Cardiomegaly (Exhibit-6 Certificate of Death, Exhibit-7 Autopsy Report).
- 7. State of Hawaii Department of Land and Natural Resources (DLNR), Division of Conservation and Resources Enforcement (DOCARE) officers and were dispatched to investigate this incident at Heeia Kea Small Boat Harbor in Kaneohe Bay involving Kaneohe Bay Ocean Sports (KBOS)/Morning Star Cruises (Exhibit-5 page 2). They interviewed and took statements from the involved crew. The Harbor Master and medical personnel at Castle Memorial Hospital were also interviewed (Exhibit-5 page 3).
- 8. On August 16, 2002, Officer met with the General Manager of KBOS, Mr. to go through an equipment familiarization and function test onboard the KBOS barge. The helmet used by Mrs. Fukuoka was connected to the air system and checked for leaks. There were no visible signs of damage to the helmet. (Exhibit-5 page 6).
- 9. On August 17, 2002, the Coast Guard (USCG) Senior Investigating Officer contacted DOCARE, Officer (Exhibit-5 page 8). Officer (Exhibit-5 page 8). Officer (Exhibit-5 page 8). Officer (Exhibit-9 State of Hawaii Property Report).
- 11. On August 18, 2002, the USCG Investigator met with DOCARE Officers and and to interview a former sales representative, Mr. (for Pylot Company (the makers of the SEATREK helmet and system), and to inquire about any available testing facility on Oahu that could conduct an inspection of the helmet and system. Mr. (stated that KBOS personnel)

Report of Investigation	Report	of	Invest	igation
-------------------------	--------	----	--------	---------

were trained and certified by Akira Konno, founder of Pylot Co., and that there is no other source available in Hawaii to do the testing. Detailed interview with Mr. followed (Exhibit-5 page 10).

- 12. The helmet was tagged as evidence and placed into storage by DOCARE Evidence Custodian, Officer that day. It was subsequently transferred to Marine Safety Office Honolulu Investigations at the request of Oahu DOCARE Branch Chief (Exhibit-12 page 1-4).
- 13. On September 23, 2002, a determination was made to return the helmet to KBOS based on several circumstances:
- -- Coroner's findings;
- -- Inability to ensure this was the actual helmet;
- -- Lack of independent manufacturer testing facilities;
- --Statement by PYLOT attesting to competency of KBOS company to conduct helmet tests (Exhibit-5 page 10).
- 14. Chemical tests performed on Mr. Mr. Mr. Mr. and Mr. and Mr. by an approved collection facility (Medical Corner, Kailua, Hawaii) proved negative (Exhibit-11 CG-2692 B).
- 15. According to a phone conversation with Mr. (KBOS General Manager), on April 21, 2003, the company (masters, deck hands, dive masters, managers) "went through everything about 1,000 times" to see if anything could have caused the accident, and came up with nothing. They now require equipment checks more frequently, like weekly checks and daily checks on specific components of the system. He also stated that, "we suspended our SEATREK operation for a few weeks".

CONCLUSION--

- 1. The investigation and findings of DOCARE are accepted by the Coast Guard (Exhibit-5 pages 11-12).
- 2. There is no evidence to suggest the diving accident was due to the action or inaction on the part of the crew or was caused by the malfunction of any part of the SeaTrek Diving system (Exhibit-5 page 12).
- 3. The victim's manner of death was accidental. Immediate cause of death was asphyxia by drowning, with contributing causes of death were Ischemic heart disease and Cardiomegaly (Exhibit-7).
- 4. Following the incident, KBOS was cooperative by allowing easy access to all records and technical information they used in the systems operation and maintenance. Throughout the investigation, KBOS voluntarily suspended their SEATREK operations, even while the State Permit remained in force.
- 5. There were no apparent violations of rules or regulations and no misconduct or negligence on the part of the master and crew.

RECOMMENDATIONS--

- 1. Although not required by Coast Guard regulation, KBOS should develop it's own Standard Operating Procedures (SOP). Doing so might aid investigators in determining the root cause of any future investigation. At the time of the accident, the SOP they had was for the SEAWALKER system.
- 2. Although not required by Coast Guard regulation, training records should be maintained for all KBOS personnel who operate or service/maintain the SEATREK system. There were no training records available for review. The records should indicate who provided training, to what standard, where and when it took place, what was covered and who attended. Doing so might aid investigators in determining the root cause of any future investigation.
- 3. Although not required by Coast Guard regulation, Pre-Operation and Post-Operation checklists should be maintained and the records kept on file as required by the SEAWALKER SOP. Doing so might aid investigators in determining the root cause of any future investigation.

/s/ BM1, USCG Assistant Investigating Officer

ENCLOSURES--

- 1) Statement of Dive Leader, Mr.
- 2) Statement of Dive Master, Mr.
- 3) Statement of Small Boat Captain, Mr.
- 4) Statement of Barge Crewman, Mr.
- 5) DOCARE Report; Case No.03/0225-OA
- 6) Copy of Certificate of Death
- 7) Autopsy Report
- 8) CG-2692, Report of Accident Injury or Death, dated 19Aug02
- 9) State of Hawaii Property Report
- 10) State of Hawaii DLNR ORMA Permit
- 11) CG-2692 B, Report of Required Chemical and Alcohol Testing
- 12) DOCARE Follow Up Report
- 13) MSO Honolulu Chain of Custody for SEATREK helmet

II. EXECUTIVE SUMMARY

Incident Summary

Activity 1665190, investigation into SEATREK Diving accident with KBOS/Morning Star Cruises Barge-HA1367, on August 14, 2002 in Kaneohe Bay, Oahu. Female passenger death. No crew or other passengers injured.

SUMMARY-- On August 14, 2002, while diving with the SEATREK system in Kaneohe Bay in 12 feet of water, Mrs. Mitsuko Fukuoka suddenly became "panicky" (exhibit-8 page 3, CG2692) and was assisted to the surface. She was transported to Castle Memorial Hospital. She died two days later (Exhibit-5 page 8).

FINDINGS--Vessel Data:

Name: HA1367CP

Flag: U.S.

Vessel Type: 24FT Barge

Operating Company: Morning Star Cruises, Inc.

49-132 Kamehameha Hwy

Kaneohe, HI 96744 Ph:(808) 239-8886


State of Hawaii: Kaneohe Bay Ocean Recreation Management Area (ORMA) Use Permit-No. O-KB-12e; Permit valid from June 28, 2002 to June 27, 2003.

Weather:

Air Temp: 75 degrees

Wind: NE Tradewinds at 0-6 mph

Visibility: Good



1. On August 14, 2002, Mrs. Mitsuko Fukuoka, a 43 year old female passenger on the Morning Star Cruises barge (HA1367) became distressed while diving with the surface supplied air 'SEATREK' helmet in Kaneohe Bay, HI. She was in approximately 12 feet of water and had been diving for about 5 minutes, when according to the dive guide, Mr. , she started giving him hand signals indicating "trouble" (Exhibit-8 CG-2692 Report of Accident, Injury or Death).

Report	of In	vestio	ation
エノしいしまし	OI III	A COTTE	auvu

- 2. The operator, Kaneohe Bay Ocean Sports (KBOS) a division of Morning Star Cruises, had a valid state use permit in-effect on the date of the incident.
- 3. The SEATREK helmet is used for underwater walking and provides positive pressure supply of air from a compressor located on the barge via a 75ft tether. The helmet is 80 lbs, white and is made of ceramic; there are no engravings or serial number on it (Exhibit-9 DOCARE Property Report).
- 4. Safety diver, Mr. second Mrs. Fukuoka to the vessel's ladder about 20 yards away to bring her to the surface. At the ladder she went "limp" and had to be carried to the surface by Mr. (Exhibit-2 Mendoza's statement).
- 5. When the helmet was removed, blood and water started coming out of Mrs. Fukuoka's nose. There was no water in the helmet. While being transported to shore via small boat, she stopped breathing and CPR was conducted by employees, Mr. and Mr. (Exhibits 3 and 4, statements of and and means).
- 6. Mrs. Fukuoka was transported to Castle Memorial Hospital, and later that evening, to the Kuakini Decompression Chamber for sickness treatment which had no effect (Exhibit-5 DOCARE Case Report pages 7 & 8). Subsequently, she died two days after the incident. The autopsy revealed that the manner of death was accidental, and listed Asphyxia by drowning as the immediate cause of death. Contributing causes of death were Ischemic heart disease and Cardiomegaly (Exhibit-6 Certificate of Death, Exhibit-7 Autopsy Report).
- 7. State of Hawaii Department of Land and Natural Resources (DLNR), Division of Conservation and Resources Enforcement (DOCARE) officers and were dispatched to investigate this incident at Heeia Kea Small Boat Harbor in Kaneohe Bay involving Kaneohe Bay Ocean Sports (KBOS)/Morning Star Cruises (Exhibit-5 page 2). They interviewed and took statements from the involved crew. The Harbor Master and medical personnel at Castle Memorial Hospital were also interviewed (Exhibit-5 page 3).
- 8. On August 16, 2002, Officer met with the General Manager of KBOS, Mr. to go through an equipment familiarization and function test onboard the KBOS barge. The helmet used by Mrs. Fukuoka was connected to the air system and checked for leaks. There were no visible signs of damage to the helmet. (Exhibit-5 page 6).
- 9. On August 17, 2002, the Coast Guard (USCG) Senior Investigating Officer contacted DOCARE, Officer to request that the state impound the helmet for testing with an external source later (Exhibit-5 page 8). Officer accepted custody of the helmet from KBOS at 1735 (Exhibit-9 State of Hawaii Property Report).
- 11. On August 18, 2002, the USCG Investigator met with DOCARE Officers and and to interview a former sales representative, Mr. , for Pylot Company (the makers of the

Rer	ort	of	Inv	esti	gati	on
エイヘト	JOIL	U.	TIIV	Cou	zu.	Our

SEATREK helmet and system), and to inquire about any available testing facility on Oahu that could conduct an inspection of the helmet and system. Mr. stated that KBOS personnel were trained and certified by Akira Konno, founder of Pylot Co., and that there is no other source available in Hawaii to do the testing. Detailed interview with Mr. followed (Exhibit-5 page 10).

- 12. The helmet was tagged as evidence and placed into storage by DOCARE Evidence Custodian, Officer that day. It was subsequently transferred to Marine Safety Office Honolulu Investigations at the request of Oahu DOCARE Branch Chief (Exhibit-12 page 1-4).
- 13. On September 23, 2002, a determination was made to return the helmet to KBOS based on several circumstances:
- --Coroner's findings;
- -- Inability to ensure this was the actual helmet;
- -- Lack of independent manufacturer testing facilities;
- --Statement by PYLOT attesting to competency of KBOS company to conduct helmet tests (Exhibit-5 page 10).
- 14. Chemical tests performed on Mr. Mr. Mr. and Mr. and Mr. and Mr. by an approved collection facility (Medical Corner, Kailua, Hawaii) proved negative (Exhibit-11 CG-2692 B).
- 15. According to a phone conversation with Mr. (KBOS General Manager), on April 21, 2003, the company (masters, deck hands, dive masters, managers) "went through everything about 1,000 times" to see if anything could have caused the accident, and came up with nothing. They now require equipment checks more frequently, like weekly checks and daily checks on specific components of the system. He also stated that, "we suspended our SEATREK operation for a few weeks".

CONCLUSION--

- 1. The investigation and findings of DOCARE are accepted by the Coast Guard (Exhibit-5 pages 11-12).
- 2. There is no evidence to suggest the diving accident was due to the action or inaction on the part of the crew or was caused by the malfunction of any part of the SeaTrek Diving system (Exhibit-5 page 12).
- 3. The victim's manner of death was accidental. Immediate cause of death was asphyxia by drowning, with contributing causes of death were Ischemic heart disease and Cardiomegaly (Exhibit-7).
- 4. Following the incident, KBOS was cooperative by allowing easy access to all records and technical information they used in the systems operation and maintenance. Throughout the investigation, KBOS voluntarily suspended their SEATREK operations, even while the State Permit remained in force.

5. There were no apparent violations of rules or regulations and no misconduct or negligence on the part of the master and crew.

RECOMMENDATIONS--

- 1. Although not required by Coast Guard regulation, KBOS should develop it's own Standard Operating Procedures (SOP). Doing so might aid investigators in determining the root cause of any future investigation. At the time of the accident, the SOP they had was for the SEAWALKER system.
- 2. Although not required by Coast Guard regulation, training records should be maintained for all KBOS personnel who operate or service/maintain the SEATREK system. There were no training records available for review. The records should indicate who provided training, to what standard, where and when it took place, what was covered and who attended. Doing so might aid investigators in determining the root cause of any future investigation.
- 3. Although not required by Coast Guard regulation, Pre-Operation and Post-Operation checklists should be maintained and the records kept on file as required by the SEAWALKER SOP. Doing so might aid investigators in determining the root cause of any future investigation.

/s/ BM1, USCG Assistant Investigating Officer

ENCLOSURES--

- 1) Statement of Dive Leader, Mr.
- 2) Statement of Dive Master, Mr.
- 3) Statement of Small Boat Captain, Mr.
- 4) Statement of Barge Crewman, Mr.
- 5) DOCARE Report; Case No.03/0225-OA
- 6) Copy of Certificate of Death
- 7) Autopsy Report
- 8) CG-2692, Report of Accident Injury or Death, dated 19Aug02
- 9) State of Hawaii Property Report
- 10) State of Hawaii DLNR ORMA Permit
- 11) CG-2692 B, Report of Required Chemical and Alcohol Testing
- 12) DOCARE Follow Up Report
- 13) MSO Honolulu Chain of Custody for SEATREK helmet

Incident Involved: Marine Casualty, Reportable

Level of Investigation: Data Collection

IMO Classification: Routine

USCG Classification: Significant Marine Casualty

Was this a Serious Marine Incident? Yes

Was a Marine Board Convened by Commandant? No

Personnel Casualty Summary

Total Missing (Active Search) = 0
Total Missing (Presumed Lost) = 0
Total Dead = 1
Total Injured = 0
Total Uninjured = 7
Total People at Risk = 8
Other Personnel (Not at Risk) = 3

Vessel(s) Status Summary

Actual Total Loss(es) = 0 Total Constructive Loss, Salvaged = 0 Total Constructive Loss, Unsalvaged = 0 Damaged = 0 Undamaged = 1

Property Damage Summary/Total Damage

Vessel(s) = \$ Cargo = \$ Facility(s) = \$ Other = \$

Waterway Mobility Summary

Vessel Delays (including speed restrictions): None

^{*} Includes estimates

Report of Investigation

III. ACTIONS IN RESPONSE TO THIS REPORT

Actions on Recommendations

Safety Alerts

IV. FINDINGS OF FACT

Subjects of the Investigation

Vessels. The following vessels were subjects of this investigation. Particulars for each vessel follow.

Vessel Name:

HA1367CP

Flag:

UNITED STATES

Vessel Identification Number:

HA1367CP

Call Sign:

Status:

Undamaged

Role:

Involved in a Marine Casualty

Vessel Class, Type, Sub-Type:

Barge, Passenger Barge, General

Gross Tonnage(GRT): Net Tonnage(NRT):

Deadweight Tons:

Length:

24

Home/Hailing Port:

Keel Laid Date:

Delivery Date:

Place of Construction:

Builder Name:

Propulsion:

Horsepower:

Master:

Classification Society:

Owner:

Operator:

MORNING STAR CRUISES

49-132 Kamehameha Hwy.

Kaneohe, HI, 96744

US

Inspection Subchapter:

Most Recent Vessel Inspection Activity:

Facilities. The following facilities were subjects of this investigation. Particulars for each facility follow.

Parties and Organizations. The following people and organizations were subjects of this investigation.

Status:

Not at Risk

Role:

Crewmember

Gender:

Age:

SSN:

Birth Date:

Email Address:

Phone Number(Home):

Address(Home/Primary Residence):



Comments:

FUKUOKA, MITSUKO

Status:

Role:

Gender:

Age:

SSN:

Birth Date:

Email Address:

Phone Number ():

Address ():

Comments:

Dead

Passenger

43

Status:

Role:

Gender:

Age:

SSN:

Birth Date:

Email Address:

Phone Number ():

Address ():

Comments:

Not at Risk

Crewmember

M

Status:

Role:

Gender:

Age:

SSN:

Birth Date:

Email Address:

Phone Number ():

Address ():

Comments:

Not at Risk Crewmember

Status:

Not at Risk

R	eport	of :	Inv	esti	gati	or
		·				~

Role:

Gender:

Age:

SSN: Birth Date:

Email Address:

Phone Number(Work):

Address(Work):

@d14.uscg.mil

Investigator

M

(808) 522-8264 293

CG MSO Honolulu 433 Ala Moana Blvd

Honolulu, HI 96813

Comments:

Supported and documented case, worked closely with State of Hawaii

DLNR officers.

Status:

Role:

Gender:

Age: SSN:

Birth Date:

Email Address:

Phone Number ():

Address ():

Comments:

Not at Risk

Reporting Party M

Status:

Role:

Gender:

Age:

SSN:

Birth Date:

Email Address:

Phone Number ():

Address ():

Comments:

Not at Risk Crewmember

M

Status:

Role: Gender:

Age:

SSN:

Birth Date:

Email Address:

Phone Number(Work):

Not at Risk

Other Agency Investigator

Μ

(808) 255-3174

Address (): Comments:

See comments for

Status:

Role:

Not at Risk

Other Μ

Gender: Age:

SSN: Birth Date:

Email Address:

Phone Number(Work):

(808) 239-8886

Address(Primary Place of Business): 49-132 Kamehameha Highway

Kaneohe, HI 96744

Comments: General Manager at KBOS, Morning

Star Cruises Inc. Submitted CG-2692

and 2692B.

Status:

Not at Risk

Role: Other Agency Investigator

Gender: M

Age:

SSN:

Birth Date: Email Address:

Phone Number(Work):

(808) 587-0077

Address():

Comments:

Officer and Officer

were the responding officers

from the State of Hawaii DLNR

agency.

Status:

Not at Risk

Role: Co-Responsible Party

Gender:

Age:

SSN:

Birth Date:

Email Address:

Phone Number(Work):

(808) 239-8886

Address(Primary Place of Business): 49-132 Kamehameha Highway

Kaneohe, HI 96744

Comments:

President of KBOS, Morning Star

Cruises Inc.

MORNING STAR CRUISES INC.

Status:

Not at Risk

Role:

Responsible Party

Email Address:

Phone Number (Work):

(808) 239-8886

Address (Primary Place of Business):

49-132 Kamehameha Highway

Kaneohe, HI 96744

Comments:

Drug and Alcohol Testing. The following people have been determined by the Coast Guard, Law Enforcement Personnel, and/or the Marine Employer to have been directly involved in a Serious Marine Incident as defined in 46 CFR 4.03-2:

; Crewmember ; Reporting Party Crewmember

Response Resources. The following incident response resources were subjects of this investigation.

Other Subjects. The following were subjects of this investigation.

Waterway Segment(s). The following waterway segment(s) were subjects of this investigation.

Heeia Kea Boat Harbor

Role: Location

Local Name: Kaneohe Bay

Description:

Incident Information

Location(s).

Description

Latitude

Longitude

Aboard Vessel: Barge-HA1367CP: Heeia Kea Boat

21 26.6 N

157 48.6 W

Harb

Sequence of Events.

08/14/2002 10:15 to 08/14/2002 11:44 (Estimated): Mitsuko Fukuoka, a 43 year old female passenger from Japan died two days after diving at Kaneohe Bay with the KBOS Seawalker activity. The autopsy report revealed the manner of death as accidental with Ischemic heart disease and Cardiomegaly as contributing factors. Immediate cause of death is asphyxia by drowning.

Event Type:

Personnel Casualties

Event Class:

Event Subclass:

Location: Known; US Waters

Description: Aboard Vessel: Barge-HA1367CP: Heeia Kea Boat Harb

Latitude: 21 26.6 N Longitude: 157 48.6 W

Subject(s) and Details:

Name

Status Type

Role

FUKUOKA,

Party Dead

Passenger

MITSUKO

Details Filed: Injury Details

Did death occur:

Yes

Was Death Immediate

No

Cause of Death:

Accidents involving submersion & suffocation (E910

Cause of Death (text): Asphyxia by drowning

Nature of Injury Causing Death:

Nature of Event Causing Death

Noncontact Injury- Diving

Date of Death Known:

Yes

Date: Date of Declared Death:

08/16/2002 08/16/2002

Declared By:

Organization:

Castle Memorial Hospital

Was Diving Involved: Commercial/Recreational:

Yes Recreational

Type of Diving: Dive Depth:

Team 15 Feet

Did injury occur: Is the Person Missing: No No

Subject to Chemical Exposure:

No

Exposed to Biological Hazards

No

Exposed to a Confined Space/Respiration Hazard:

No

Exposed to Other Hazards:

No

Narrative Summary:

Mrs. Mitsuko Fukuoka a 43 year old visitor from Japan suffered an asphyxia incident while diving with KBOS Seawalker diving out of Heeia Harbor, Kaneohe, Hawaii on August 14, 2002. She was taken to Castle Memorial Hospital where she passed away two days later.

Drug testing and alcohol test were performed immediately following the incident. Drug and

Alcohol test were given to

. All test were

08/20/2002 17:30 to 08/20/2002 17:30 (Known): Drug and Alcohol test (NEG)

Action Type:

Other Actions - Drug and Alcohol Use and Testing

Action Class:

Take Drug Test - Post-casualty

Location: Unknown

Subject(s) and Details:

Name

Type

Status

Role

Party

Not at Risk

Crewmember

Details Filed: Drug and Alcohol Test Details

Sample Collection

Reason for Sample:

Post-casualty

Date/Time Directed:

08/20/2002 5:30:00 PM

Means of Direction:

Directed By:

Organization:

U.S. Coast Guard

Description:

Directed to get DOT Test:

Yes

Chemical Test Sample Provided: Chemical Test Type:

Yes Both

Sample Type:

Urine

Date/Time Sample Taken: 08/20/2002 5:30:00 PM

Onsite Kailua

Sampling Location:

Yes

DOT Protocols Used:

Collection Agent: Donor Certified: Irregularities Noted:

Yes No

Transferred/Chain of

Custody Complete:

Yes

Field Sobriety Test

Field Sobriety Test Performed:

No

Alcohol Analysis

Method of Analysis: Instrument Used:

Breath Test BAT

Date/Time Results Obtained:

08/20/2002 5:17:00 PM

Results:

Agency Conducting Analysis:

Reliable Drug Testing

Description of Analysis: Irregularities in Analysis:

000. No

Yes

Drug Analysis

Analyzing Laboratory:

NORTHWEST DRUG TESTING, A DIVISION OF

NWT, SALT LAKE CITY, U

DOT Protocols Used:

Test Results:

Medical Review Officer/Coroner:

MRO/Coroner Conclusions: Sample Transferred and Chain

of Custody Complete:

Drug Re-Analysis

Yes

08/20/2002 17:35 to 08/20/2002 17:35 (Known): Drug and Alcohol test (NEG)

Action Type:

Other Actions - Drug and Alcohol Use and Testing

Action Class:

Take Drug Test - Post-casualty

Location: Unknown

Subject(s) and Details:

Name

<u>Type</u>

Status

Role

Party

Not at Risk

Reporting Party

Details Filed: Drug and Alcohol Test Details

Sample Collection

Reason for Sample:

Post-casualty

Date/Time Directed:

08/20/2002

Means of Direction:

Directed By:

Organization:

U.S. Coast Guard

Description:

Directed to get DOT Test:

Yes

Chemical Test Sample Provided:

Yes

Chemical Test Type:

Both

Sample Type:

Urine

Date/Time Sample Taken: 08/20/2002 5:35:00 PM

Onsite Kailua

Sampling Location:

Yes

DOT Protocols Used: Collection Agent:

Yes

Donor Certified: Irregularities Noted:

No

Transferred/Chain of Custody Complete:

Yes

Field Sobriety Test

Field Sobriety Test Performed:

No

Alcohol Analysis

Method of Analysis:

Breath Test

Instrument Used:

BAT

Date/Time Results Obtained:

08/20/2003 5:22:00 PM

Results:

Agency Conducting Analysis:

Reliable Drug Testing

Description of Analysis: Irregularities in Analysis: .000 No

Drug Analysis

Analyzing Laboratory:

NORTHWEST DRUG TESTING, A DIVISION OF

NWT, SALT LAKE CITY, U

DOT Protocols Used:

Yes

Dr.

Test Results:

Medical Review Officer/Coroner:

MRO/Coroner Conclusions: Sample Transferred and Chain

of Custody Complete:

Yes

Drug Re-Analysis

08/20/2002 17:50 to 08/20/2002 17:50 (Known): Drug and Alcohol test (NEG)

Action Type:

Other Actions - Drug and Alcohol Use and Testing

Action Class:

Take Drug Test - Post-casualty

Location: Unknown

Subject(s) and Details:

Name

Type Party Status

Role

Not at Risk

Crewmember

Details Filed: Drug and Alcohol Test Details

Sample Collection

Reason for Sample:

Post Accident

Directed to get DOT Test:

Yes

Chemical Test Sample Provided:

Yes

Chemical Test Type:

Dangerous Drugs

Urine

Sample Type:

Date/Time Sample Taken: 08/20/2002 5:50:00 PM

Sampling Location:

Onsite Kailua

DOT Protocols Used: Collection Agent: Donor Certified: Irregularities Noted: Transferred/Chain of

Custody Complete:

Yes

Yes

Yes

Field Sobriety Test

Field Sobriety Test Performed:

Alcohol Analysis

Method of Analysis: Instrument Used:

BAT Date/Time Results Obtained:

Results:

Agency Conducting Analysis: Description of Analysis:

Irregularities in Analysis:

Drug Analysis

Analyzing Laboratory:

NWT, SALT LAKE CITY, U DOT Protocols Used:

Test Results:

Medical Review Officer/Coroner: Dr.

MRO/Coroner Conclusions: Sample Transferred and Chain of Custody Complete:

Drug Re-Analysis

No

No

Breath Test

08/20/2002 5:47:00 PM

Reliable Drug Testing

.000 No

NORTHWEST DRUG TESTING, A DIVISION OF

Yes

Yes

V. CAUSAL ANALYSIS

The Initiating Event of the Incident

Initiating Event:

Personnel Casualties (08/14/2002 10:15:00 AM)

Production Factors

Preconditions

LUCs in People - Limitations of the person - Physical conditions

Workplace Factors

LUCs in Supervision - Inadequate tracking of qualifications LUCs in Supervision - Inadequate tracking of performance LUCs in Operations - Operations not in accordance with rules and regulations

Organization Factors

LUCs in Human Resources - Inadequate Training (of Line Managers) LUCs in Procedures - Inadequate standards LUCs in Procedures - Inadequate documentation LUCs in Regulations - Inadequate or absent regulations

Defense Factors

Defenses that were in place but failed due to inadequacy - Inadequate training Defenses that could reasonably have been expected but were never put in place - Absence of training

Failures of Defense Against Subsequent Events in the Incident

Case 1:03-cv-00672-SOM-BMK Document 96-3 Filed 09/20/2006 Page 22 of 27

Report of Investigation

VI. REFERRAL FOR ENFORCEMENT ACTION

The following referrals for enforcement action have been made as a result of this investigation and represent those instances where the Coast Guard has gathered evidence that indicates one or more alleged violations or offenses may have occurred. Any determinations as to whether or not one or more actual violations or offenses have occurred are documented in the appropriate Coast Guard enforcement activities.

APPENDIX 1 - EVIDENCE

ECN 1665190 #10 : Document/Written Statement

Crewman

Collection Information:

Date/Time:

08/14/2002 10:30:00 AM

Location:

Heeia Harbor

Collected By: 3rd Party Gathered; Officer , State of Hawaii

DLNR/DOCARE

Witnessed By: 3rd Party Witness;,

Tracking: Attachments:

ECN 1665190 #11 : Document/Written Statement

Crewman

Collection Information:

Date/Time:

08/14/2002 10:35:00 AM

Location:

Heeia Harbor

Collected By: 3rd Party Gathered; Officer , State of Hawaii

DLNR/DOCARE

Witnessed By: 3rd Party Witness;,

Tracking:

Attachments:

ECN 1665190 #12 : Document/Written Statement

Crewman

Collection Information:

Date/Time:

08/14/2002 2:05:00 PM

Location:

Heeia Harbor

Collected By: 3rd Party Gathered; Officer State of Hawaii

DLNR/DOCARE

Witnessed By: 3rd Party Witness;,

Tracking:

Attachments:

ECN 1665190 #13 Document/Other Municipal Agency Documents

13-page report from DLNR/DOCARE Officers

and

Collection Information:

Date/Time:

08/19/2002 12:00:00 PM

Location:

MSO Honolulu

Collected By: USCG Gathered; BM1 HONMS

Witnessed By: USCG Witness;,

Tracking:

Attachments:

ECN 1665190 #14 Document/Other Municipal Agency Documents

Closing report from DLNR/DOCARE Officer

Collection Information:

Date/Time:

09/25/2002 11:30:00 AM

Location:

MSO Honolulu

Collected By: USCG Gathered; BM1 HONMS

Witnessed By: USCG Witness;,

Tracking: Attachments:

ECN 1665190 #15 : Document/Chain of Custody

FDTCCF/

2 Pages

Collection Information:

Date/Time:

08/13/2003 10:08:00 AM

Location:

MSO Honolulu, INV

Collected By: USCG Gathered; YN2

Witnessed By: USCG Witness;,

Tracking: Attachments:

ECN 1665190 #16 : Document/Chain of Custody

FDTCCF/

Collection Information:

Date/Time:

08/13/2003 10:08:00 AM

Location:

MSO Honolulu, INV

Collected By: USCG Gathered; YN2

Witnessed By: USCG Witness;,

Tracking: Attachments:

ECN 1665190 #17 : Document/Chain of Custody

FDTCCF/

2 pages

Collection Information:

Date/Time:

08/13/2003 10:08:00 AM

Location:

MSO Honolulu

Collected By: USCG Gathered; YN2

Witnessed By: USCG Witness;

Tracking: Attachments:

ECN 1665190 #2 Document/Other Document

State of Hawaii Department of Health: Certificate of Death, Mitsuko Fukuoka

Collection Information:

Date/Time:

08/20/2002 2:01:00 PM

Location:

MSO Honolulu

Collected By: USCG Gathered; BM1 HONMS

Witnessed By: USCG Witness;,

Tracking:

Attachments:

ECN 1665190 #3 : Document/Chain of Custody

MSO Honolulu COC for the SeaTrek Helmet

Collection Information:

Date/Time:

09/13/2002 3:45:00 PM

Location:

MSO Honolulu

Collected By: USCG Gathered; BM1 HONMS

Witnessed By: USCG Witness;,

Tracking:

Attachments:

ECN 1665190 #4 Document/Other Document

Department of the Medical Examiner City and County of Honolulu: Autopsy Report Case

No. 02-1079

Collection Information:

Date/Time:

08/20/2002 2:08:00 PM

Location:

MSO Honolulu

Collected By: USCG Gathered; BM1 HONMS

Witnessed By: USCG Witness;,

Tracking:

Attachments:

ECN 1665190 #5 Document/CG-2692 Report of Marine Accident, Injury or Death

Submitted by KBOS General Manager

Collection Information:

Date/Time:

08/19/2002 3:43:00 PM

Location:

MSO Honolulu

Collected By: USCG Gathered; LT HONMS

Witnessed By: USCG Witness;,

Tracking:

Attachments:

ECN 1665190 #6 Document/CG-2692B Rpt of Req Chemical Drug/Alcohol Testing

results of drug tests on KBOS crew.

Collection Information:

Date/Time:

08/20/2002 5:58:00 PM

Location:

MSO Honolulu

Collected By: USCG Gathered; LT HONMS

Witnessed By: USCG Witness;

Tracking:

Attachments:

ECN 1665190 #7 : Document/Written Statement

Captain

Collection Information:

Date/Time:

08/14/2002 10:40:00 AM

Location:

Heeia Harbor

Collected By: 3rd Party Gathered; Officer State of Hawaii

DLNR/DOCARE

Witnessed By: 3rd Party Witness;,

Tracking:

Attachments:

ECN 1665190 #8

: Document/Written Statement

Crewman

Collection Information:

Date/Time:

08/14/2002 10:40:00 AM

Location:

Heeia Harbor

Collected By: 3rd Party Gathered; Officer, State of Hawaii

DLNR/DOCARE

Witnessed By: 3rd Party Witness;

Tracking:

Attachments:

ECN 1665190 #9 : Document/Written Statement

Crewman

Collection Information:

Date/Time:

08/14/2002 10:35:00 AM

Location:

Heeia Harbor

Collected By: 3rd Party Gathered; Officer , State of Hawaii

DLNR/DOCARE

Witnessed By: 3rd Party Witness;,

Tracking:

Attachments:

ECN1665190 #1 : Document/Chain of Custody

State of Hawaii DLNR/DOCARE Property Report: SeaTrek Diving Helmet

Collection Information:

Date/Time:

08/17/2002 5:48:00 PM

Location:

Heeia Harbor, Kaneohe Bay

Collected By: 3rd Party Gathered; Officer State of Hawaii

DLNR/DOCARE

Witnessed By: 3rd Party Witness; Officer , State of Hawaii

DLNR/DOCARE

Tracking:

Attachments:

APPENDIX 2 - CORRESPONDENCE

(KBOS) to ASIO, information on SeaTrek Manufacturer, 8/30/02 7586 - Fax from

Source:

3rd Party

Type:

Incoming

Received:

At MSO Honolulu on 08/30/2002 9:59:00 AM

Attachments:

7592 - Honolulu Advertiser article posted on Tuesday, August 20, 2002. Title: "Tourist's

Advertiser Staff Writer Seawalker death a mystery" by

Source:

3rd Party

Type:

Incoming

Received:

At MSO Honolulu on 08/20/2002 1:25:00 PM

Attachments:

7593 - Letter of correction and patents from on behalf of

President. Seawalker, Tokyo, Japan. August 26, 2002.

Source:

3rd Party

Type:

Incoming

Received:

At MSO Honolulu on 08/26/2002 1:33:00 PM

Attachments: